



ATLANTIC ENGINEERING CONSULTANTS LTD.

ENGINEERS & PROJECT MANAGERS

November 23, 2015

Mr. Jarvis Hulan
General Services Supervisor
Dept of Facilities Management
Sir Wilfred Grenfell College
University Drive
Corner Brook, NL A2H 6P9

Dear Jarvis:

RE: SWIMMING POOL DECK DETERIORATION – STRUCTURAL INVESTIGATION

Further to our report of October 26, 2015, we would add the following comments for your information and consideration.

While our most recent investigation has determined that corrosion of the reinforcing steel is still active and will, in all probability, continue, structural integrity has not yet been compromised to the level of imminent danger. As corrosion continues however, this level will be approached.

Our latest report indicates that rehabilitation should be carried out “at the earliest opportunity”. In our professional opinion, we believe the end of this academic year (Spring 2016) would be an appropriate time to address this situation. Any delay beyond this time would be unwise and introduces an element of risk that we believe is not acceptable.

Trusting our comments will be of assistance.

Yours truly,

ATLANTIC ENGINEERING CONSULTANTS LIMITED

Donald J. DiCesare, P. Eng.

Lb

Enc.

34 Main Street
Corner Brook, NL
A2H 1C3

Telephone (709) 634-3612
Fax (709) 634-4628
djdiculare@aecl.nfld.net